SPECIAL AIRWORTHINESS INFORMATION BULLETIN



U.S. Department of Transportation

Federal Aviation Administration

No. CE-02-14 February 13, 2002

Aircraft Certification Service Washington, DC

We post SAIBs on the internet at "av-info.faa.gov"

This is information only. Recommendations are not mandatory.

INTRODUCTION

The purpose of this Special Airworthiness Information Bulletin is to advise owners/operators of certain Grob G115 series airplanes of the need to review the service bulletins listed below.

BACKGROUND

The Small Airplane Directorate, Aircraft Certification Service, of the Federal Aviation Administration (FAA) conducted a review of certain Grob G115 series airplane service bulletins. The purpose of the review was to evaluate each service bulletin to determine the continued airworthiness safety aspect. The options considered by the FAA included: mandated compliance by an FAA Airworthiness Directive (AD), various forms of notices, or no further action required.

Owners/operators of Grob G115 series airplanes should also note that there have been Airworthiness Directives issued against these airplanes concerning other safety issues.

RECOMMENDATIONS

The service bulletins identified in this document are not considered appropriate for AD action at this time; however, the FAA strongly suggests that all owners/operators of the Grob G115 series airplanes review their compliance with the service bulletins listed below.

Grob Luft and Raumfahrt G115 Airplane Series Service Bulletin Number	MODEL	DATE	TITLE
MSB1078-103	G115D, G115E, G115EG	10/3/01	Baggage Compartment Cover
MSB1078-114	G115EG	9/24/01	Avionic Rack Installation

THE SERVICE BULLETINS CAN BE OBTAINED FROM

Head of Product Support
GROB Luft- und Raumfahrt
Lettenbachstrasse 9
D-86874 Tussenhausen-Mattsies
Germany
011-49-8268-998139 telephone
011-49-8268-998200 facsimile
productsupport@grob-aerospace.de email

FOR FURTHER INFORMATION CONTACT

Karl M. Schletzbaum, Aerospace Engineer, FAA, Project Support Branch (ACE-112), Small Airplane Directorate, 901 Locust Street, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090; email: karl.schletzbaum@faa.gov.